

5/027/0111
Outgoing
Peter Brinton <peterbrinton@utah.gov>

New 6 reclamation costs

Peter Brinton <peterbrinton@utah.gov>

Tue, Dec 4, 2012 at 5:12 PM

To: Kevin Rasmussen <rasmussenex@hotmail.com>

Cc: Paul Baker <paulbaker@utah.gov>

Hi Kevin,

Here are a few photos of the site conditions on the day we visited the site (Wed Nov 7th), if it's of help in determining what happened when.

The equipment were working on the east pit and dumps. The pickup shown in the photo had the last of the trash to remove from the site, and that trash was transferred to the end dump before I left.

There is still a small amount of scrap, actually, one part of a vehicle bumper and something else. See the last photo DSCN4207 in the middle toward the top, though it's kindof hard to see. I assumed that it had been uncovered during the regrading on the last day, since I didn't see it on Wed, Nov 7th. We found it on the regraded slope on the day we returned to seed. That makes me think the end dump wasn't around to haul it off on Thurs, Nov 8th. Jerry and I are fine with it left there, as it's minor. We or the BLM can get it with a pickup one of these days.

Uncovered trash makes me wonder if we should have you dig for more trash out there... Just kidding - it was minor. Thanks for checking into this.

Peter

On Tue, Dec 4, 2012 at 4:28 PM, Peter Brinton <peterbrinton@utah.gov> wrote:

o

-

Peter Brinton
Environmental Scientist/Engineer II
Utah Division of Oil, Gas & Mining
Office Phone: 801-538-5258
Days: M - Th, Every Other Friday
Hours: 7:30am - 5:00pm

7 attachments



DSCN4182.JPG
741K



DSCN4160.JPG
724K



DSCN4165.JPG
738K



DSCN4166.JPG
736K



DSCN4157.JPG
707K